


# WIRING DIAGRAM



Q-OVERLOAD PROTECTOR  
R-START RELAY

\*GRN OR GRN WITH YELLOW TRACER